





3.2mm diameter implant in a 5mm site
does not allow enough bone for
adequate remodeling



A narrow diameter 2.5mm implant
allows for thicker bone and
appropriate remodeling



Long term outcome using 1.9mm implant



2018

2019 OCTOBER



2019 October 11 years post